



UNITÉS DE FUSION

RÉFÉRENCE OEM	RÉFÉRENCE CMB	DÉSIGNATION
RM1-6406	NEU2000	HP P2055 Fuser Maintenance Kit
RM1-6319	NEU2001	HP P3015 Fuser Maintenance Kit
CB389A	NEU2002	HP P4014/P4015/P4515 Fuser Maintenance Kit
Q2430A	NEU2004	HP4200 Fuser Maintenance Kit
Q2437A	NEU2005	HP4300 Fuser Maintenance Kit
Q5422A	NEU2006	HP4250/4350 Fuser Maintenance Kit
C9726A	NEU2007	HP4600 Image Fuser Kit
Q3677A	NEU2008	HP4650 Image Fuser Kit
Q7503A	NEU2009	HP4700/4730 Image Fuser Kit
Q3985A	NEU2010	HP5550 Fuser Maintenance Kit
Q7833A	NEU2018	HPM5025/M5035 Fuser Maintenance Kit
CE506A	NEU2011	HPCM3530/CP3525/M551 Fuser Maintenance Kit
CE247A	NEU2012	HPCP4025/4525 Maintenance Kit
C9153A	NEU2014	HP9000 Fuser Maintenance Kit
56P2544	NEU2015	Lexmark T630 Fuser Maintenance Kit
40X2590	NEU2016	Lexmark T640 Fuser Maintenance Kit
40X1871	NEU2017	Lexmark T650 Fuser Maintenance Kit